



Central Valley Regional Water Quality Control Board

25 March 2015

NOTICE OF VIOLATION

Jennifer Brady
E&B Natural Resources Management Company
3000 James Road
Bakersfield, CA 93308

CERTIFIED MAIL 7014 2870 0000 7593 4825

INSPECTION REPORT – E&B NATURAL RESOURCES MANAGEMENT COMPANY, GOVERNMENT LEASE, POSO CREEK OIL FIELD, KERN COUNTY

Central Valley Regional Water Quality Control Board staff (Staff) inspected the Government Lease in the Poso Creek Oil Field on 11 December 2014 to ascertain the status of three surface impoundments (sumps) identified by the California Division of Oil, Gas, and Geothermal Resources (DOGGR) as active. Disposal operations at the facility are not regulated by Waste Discharge Requirements (WDRs). Staff's comments are presented in the enclosed inspection report.

Three unlined sumps were observed. During the inspection, Staff observed an active discharge of fluid into Sump #1. Sumps #1 and #2 are connected via an overflow pipe. Oil stained soil, oil field produced wastewater, and oil on the fluid surface was observed in Sumps #1 and #2. The discharge of wastewater to a sump without WDRs is a violation of Section 13260(a) of the California Water Code. Freeboard and netting appeared to be adequate.

Oil stained soil and fluid was observed in Sump #3. The fluid had a small volume of oil and had a total depth of approximately 2 inches. Troyce Leatherwood with E&B Natural Resources stated the fluid in Sump #3 is from a recent rain event, but did not have documentation that it was rainwater. Staff was unable to sample the fluid due to the steep side slope and sample pole was insufficient in length. Sumps used for the disposal of oil field produced wastewater normally have elevated concentrations of salts in the soil. Rainwater allowed to pond on a sump floor provides an opportunity for the salts to dissolve into the fluid creating wastewater. Wastewater in a sump without WDRs is a violation of Section 13260(a) of the California Water Code.

If E&B Natural Resources intends to retain the sumps for the discharge of waste, a Report of Waste Discharge (RWD), along with the appropriate filing fee, needs to be submitted for issuance of WDRs. The discharge of wastes to a sump without WDRs, or before 140 days following a determination that the submitted RWD is complete and adequate, is a violation of Section 13260 of the California Water Code (CWC). The RWD needs to include a demonstration that the California Environmental Quality Act (CEQA) has been satisfied. A violation of 13260(a) of the CWC may subject E&B Natural Resources to potential liability pursuant to CWC Section 13350 or 13261, in an amount up to \$10 for

KARL E. LONGLEY SCD, P.E., CHAIR | PAMELA C. CREEDON P.E., BCEE, EXECUTIVE OFFICER

each gallon discharged or \$5,000 for each day that the discharge occurs, and/or up to \$1,000 for each day the RWD is not submitted.

2

If E&B Natural Resources plans to close the sumps, please submit closure plans prepared by a California registered professional. In addition, please submit a history of waste discharge (volumes & dates) to the sumps.

If you have any questions regarding this inspection, please contact Josh Mahoney at (559) 444-2449 or by email at <u>Joshua.Mahoney@waterboards.ca.gov</u>

DANE S. JOHNSON

Senior Engineering Geologist Professional Geologist No. 4239

Enclosure:

Inspection Report

cc: Mike Toland, CDOG&GR, Bakersfield

5F		N/A				UN-REG	1/5	
OFFIC	_	WDID	- FACII	LITIES INSPEC	TION -	PROGRAM	PAGE NO.	
N/A		399870	_	REPORT		14262	813144	
ORDER I	NO.	REG MEASURE ID				PARTY ID	PLACE ID	
E&BN	IATURAL RE	SOURCES MANA	GEMENT COM	1PANY P	OSO CREEK (OIL FIELD; GOVERN	MENT LEASE	
		DISCHARGER NAME				FACILITY NAME		
	3	3000 JAMES ROAL)		SECTION 14 T27S, R27E, MDB&M			
	DAI	STREET ADDRESS	2000		STREET ADDRESS			
	BAr	(ERSFIELD, CA 93 CITY, STATE, ZIP CODE	3308		KERN COUNTY			
		JENNIFER BRADY	,		CITY, STATE, ZIP CODE JENNIFER BRADY			
		CHARGER CONTACT PER				ACILITY CONTACT PERSON		
(661) 6	16 - 6168	,	bresources.co	es.com (661) 616 - 6168		jbrady@ebresources.com		
	HONE NO.		AIL ADDRESS				E-MAIL ADDRESS	
Inspection 12/11/201		pe Compliance Ins		NSPECTION INF		ad Inspector:Josh [<i>M</i> ahoney	
IN	SPECTION DATE(S	ins	PECTION TIME		GENERAL V	VEATHER CONDITIONS		
			INS	SPECTION ATTENDEE	(S)			
Je	osh Mahone	у Се	ntral Valley V	Vater Board (559) 445-5116	Joshua Mahor	Joshua.Mahoney@waterboards.ca.gov	
	NAME	•	COMPANY/AC		TELEPHONE NO.		MAIL ADDRESS	
Troy	ce Leatherw	ood E	&B Natural F			<u> </u>		
	NAME		. COMPANY/AC	GENCY	TELEPHONE NO.	E-M	MAIL ADDRESS	
	NAME		COMPANY/AC	GENCY	TELEPHONE NO.	E-N	MAIL ADDRESS	
	INS	PECTION SUM	MARY (fo	r CIMOS antru	- 500 chai	racter maximu	m)	
		·	·	by Waste Discharg	'			
,								
Identify VIO	LATIONS noted be violation, an		table below. Fo	ATIONS SUMM r each violation docume ter Code violated.	, , ,	plicable) o CIWQS, identify Viola	tion ID and Violation	
Label	Violation ID	Violation	Туре	Violation Description		Se	ection of the WDRs Violated	
V1	986623	Unauthorized	Discharge Flu	uid observed in Sumps	#1, #2, and #3		O(a) of California r Code	
V2								
V3								
V4								
V5								
V6					-			
			OTHER VIO	OLATIONS (if a	pplicable)			
SMR violati	ons?	☐ Yes ☐ No ☒	Not Evaluated	Notes:				
File Review	violations?	☐ Yes ☐ No ☒	Not Evaluated	Notes:				
Lead Insp			gnature:	J MI)		e: <u>3/25/15</u>	
mahacmon I	racking Inform	ation Reviewed	l by: (1)	- A/	(2)	(3)	CIWQS Coordinator	
Filename:		esources, Governmen		/ WQS Entry Date:	2/18/2015	CIWQS Inspection ID		

FACILITIES INSPECTION REPORT

E&B NATURAL RESOURCES MANAGEMENT GOVERMENT LEASE, POSO CREEK OIL FIELD

	FACILITY IN	FORMATION				
Crude oil production facility. Tank farm w		paration tanks.		Active		
FACILITY DESCRIPTION (e.g., total area in acres, number of waste	STAT	STATUS (active, inactive, closed)				
Oil field production wastewater.				Oil/Gas Extraction		
WASTE TYPES			FACII	LITY CLASSIFICATION		
Wastewater piped to injection wells and s DISPOSAL DESCRIPTION (e.g., composting, landfill, surface impour				-		
DIST OSAL DESCRIPTION (e.g., composting, landing, surface impour	-					
	BACKG		···			
The sumps on the lease are operated by lease previously inspected.	E&B Natural Resou	rces and are curre	ntly unregulated.	The lease has not		
	INSPECTION	N GIS DATA				
GIS Equipment used:						
MANUFACT	URER	MODEL	SERIAL NO.	DATUM		
Description of Measured Point	Latitude	Longitude	Datum	Comments		
Centroid of Sump #1	35°35'11.94"N	119° 2'37.19"W	NAD 83	Active – Recorded by the DOGGR		
Centroid of Sump #2	35°35'11.93"N	119° 2'38.18''W	NAD 83	Active – Recorded by the DOGGR		
Centroid of Sump #3	35°35'4.16"N	119° 2'41.71"W	NAD 83	Idle – Recorded by the DOGGR		
	·					
Describe observations and findings and identify those identifying the cited violation number within parenthes. The Government Lease (Facility) in the Poidentified by the DOGGR as active and idl Photographs were taken to document con. The Facility contains a tank farm (Photografluid was observed in Sumps #1 and #2. I Sump #1 (Photograph 4). The freeboard at the fluid was not collected due to the thick Sumps #1 and #2. Sump #3 is located approximately 0.15 mi and fluid was observed in Sump #3. The finches. Troyce Leatherwood with E&B National documentation to verify it was rainwater. fluid due to the steep side slope and samp produced wastewater normally has elevated sump floor provides the opportunity for the sump without WDRs is a violation of Section Inlet pipes were observed in Sump #3, although the pipes were observed in Sump #3.	pes following the observations of Creek Oil Field the Disposal operated ditions observed (supply and three suburing the inspection of the oil layer the south of Sumpselvid had a small volumal Resources stated the fluid had an oil the oil layer of the oil layer of the oil	ation/finding (e.g., Expowas inspected to a ions at the Facility aree page 4). Imps (Photographs on, Staff observed a ps #1 and #2 appear on the surface. Make #1 and #2, on the lume of oil and had ated the fluid in the sysheen. Staff was ent in length. A surf salt in the soil. Report to the fluid creating California Water Country of origin of the point of origin of the salt in the soil.	sed waste on top dec scertain the statu are not regulated 3, 5, and 7). Oil an active discharge ared to be adequated bultiple inlet pipes Government Lea a total depth of sump is rainwate unable to obtain mp used for the cainwater allowed g wastewater. Woode.	ck (V1)). us of three sumps I by WDRs. I stained soil and ge of fluids into uate. A sample of swere observed in ase. Oil stained soil approximately 2 er, but did not have a sample of the disposal of oil field to pond on the fastewater in a		
			·			
SAMPLING INFORMATION AND OBSERVATIONS						
,	☐ Yes No	Are sample results	included in report?	☐ Yes No		

FACILITIES INSPECTION REPORTE&B NATURAL RESOURCES MANAGEMENT GOVERMENT LEASE, POSO CREEK OIL FIELD

SAMPLE COLLECTION INFORMATION AND OBSERVATIONS

		•		
SAMPLE ID	SAMPLE DESCRIPTION/OBSERVATIONS	SAMPLE TIME (hours)	РНОТО NO.	
SAMPLE ID	SAMPLE DESCRIPTION/OBSERVATIONS	SAMPLE TIME (hours)	PHOTO NO.	
SAMPLE ID	SAMPLE DESCRIPTION/OBSERVATIONS	SAMPLE TIME (hours)	PHOTO NO.	
SAMPLE ID	SAMPLE DESCRIPTION/OBSERVATIONS	SAMPLE TIME (hours)	PHOTO NO.	
	DISCUSSION OF SAMPLING RESULTS			
iscuss sampling results (e.g., dis	cuss whether sampling results show compliance with WDRs).			
lo samples were collected				

CONCLUSIONS

Summarize the conclusions of the inspection(s) below.


- 1. Sumps #1 and #2 are actively being used for the disposal of oil field produced wastewater.
- 2. Sump #3 has the potential to be used for the disposal of oil field produced wastewater. The stated purpose of Sump #3 is emergency containment of fluids from above ground storage tanks.
- 3. Fluid was observed in Sumps #1, #2, and #3.
- 4. Oil field produced wastewater generated at the Facility is piped to an injection well or Sumps #1 and #2 for disposal.

FACILITIES INSPECTION REPORT E&B NATURAL RESOURCES MANAGEMENT GOVERMENT LEASE, POSO CREEK OIL FIELD


PHOTOGRAPHS




Photograph 1. - Aerial of the facility (2014).



Photograph 2. - View of tank farm looking southwest.



Photograph 3. – View of Sump #1 looking southeast.



Photograph 4. – View of Sump #1 active discharge.



Photograph 5. – View of Sump #2 looking south.




Photograph 6. - View of fluid in Sump #2.


FACILITIES INSPECTION REPORT

E&B NATURAL RESOURCES MANAGEMENT GOVERMENT LEASE, POSO CREEK OIL FIELD

PHOTOGRAPHS



Photograph 7. – View of Sump #3 looking north.



Photograph 8. – View of the fluid in Sump #3.



Photograph 8. - View of tank with pipes disconnected.